



Environmental Protection Agency Region X-Idaho Operations Bureau 1435 N. Orchard Boise, ID 83706 October 7, 2014

RE: Phase I Environmental Site Assessment

Mountain View Equipment

1203 Garber Street, Caldwell, Idaho

To Whom It May Concern:

Summit Environmental, Inc. (Summit) has been retained to conduct an environmental site assessment on the property at 1203 Garber Street in Caldwell, Idaho, Idaho (see attached aerial map). The site is the location of Mountain View Equipment, a agriculture equipment sales and service business.

An aerial map with the site location indicated is attached for your assistance. If you have any questions about the site location please, contact Summit at 208.377.2900.

We would appreciate any available information your office might have regarding environmental contamination at the sites, or any nearby properties that may impact the sites. Information regarding any area or regional environmental concerns that may potentially impact the sites would also be beneficial.

Information pertinent to Summit's assessment would include, but not be limited to: chemical spill notifications, employee or citizen complaints regarding chemical management, noncompliance with environmental regulations (RCRA, CERCLA, etc.), leaking underground storage tanks, groundwater and drinking water information, sewer/septic and waste water information, or any current or past environmental investigations associated with this area.

Please call me at 208.377.2900 if you have any questions or need further information. A written response addressed to me prior to October 24, 2014 would be greatly appreciated. Please reference the site in your correspondence.

Sincerely,

Summit Environmental, Inc.

Mike Larango, CES Field Supervisor

y leid Superviso

Attachment

